

Port of Dampier – Dampier Sea Buoy, temporary change of light characteristics

Number: D03/2025(T)


Date: 28/01/2025

Date of effect:	28/01/2025
Details:	Port of Dampier - Sea Buoy – Change of light characteristics
Former notice:	NA
Charts and publications:	AUS 57, 59 ENC Cell – AU5058P0
Further notice:	Will be cancelled on rectification and new marine notice issued
Attachments:	Charlet of the location of the buoy

Mariners are advised that light colour characteristic of Navigation Aid Dampier Sea Buoy has been temporarily changed to white.

Name	Latitude	Longitude	New Colour	New Light Characteristic
Dampier Sea Buoy Racon M AIS	20° 25.428' S	116° 42.976' E	White	Q(4).6s

New marine notice will be issued once the yellow light is reinstated.



**Capt. Mike Minogue
Harbour Master**